ARM Instruction Set
Quick Reference Card

Key to Tables	
{cond}	Refer to Table **Condition Field {cond}**
<Oprnd2>	Refer to Table **Operand 2**
<fields>	Refer to Table **PSR fields**
{S}	Updates condition flags if S present
C*, V*	Flag is unpredictable after these instructions in Architecture v4 and earlier
Q	Sticky flag. Always updates on overflow (no S option). Read and reset using MRS and MSR
x,y	B meaning half-register [15:0], or T meaning [31:16]
<immed_8r>	A 32-bit constant, formed by right-rotating an 8-bit value by an even number of bits
<immed_8*4>	A 10-bit constant, formed by left-shifting an 8-bit value by two bits

<a_mode2>	Refer to Table **Addressing Mode 2**
<a_mode2P>	Refer to Table **Addressing Mode 2 (Post-indexed only)**
<a_mode3>	Refer to Table **Addressing Mode 3**
<a_mode4L>	Refer to Table **Addressing Mode 4 (Block load or Stack pop)**
<a_mode4S>	Refer to Table **Addressing Mode 4 (Block store or Stack push)**
<a_mode5>	Refer to Table **Addressing Mode 5**
<reglist>	A comma-separated list of registers, enclosed in braces ({ and })
{!}	Updates base register after data transfer if ! present
§	Refer to Table **ARM architecture versions**

Operation		§	Assembler	S updates	Q	Action	Notes
Move	Move		MOV{cond}{S} Rd, <Oprnd2>	N Z C		Rd := Oprnd2	
	NOT		MVN{cond}{S} Rd, <Oprnd2>	N Z C		Rd := 0xFFFFFFFF EOR Oprnd2	
	SPSR to register	3	MRS{cond} Rd, SPSR			Rd := SPSR	
	CPSR to register	3	MRS{cond} Rd, CPSR			Rd := CPSR	
	register to SPSR	3	MSR{cond} SPSR_<fields>, Rm			SPSR := Rm (selected bytes only)	
	register to CPSR	3	MSR{cond} CPSR_<fields>, Rm			CPSR := Rm (selected bytes only)	
	immediate to SPSR	3	MSR{cond} SPSR_<fields>, #<immed_8r>			SPSR := immed_8r (selected bytes only)	
	immediate to CPSR	3	MSR{cond} CPSR_<fields>, #<immed_8r>			CPSR := immed_8r (selected bytes only)	
Arithmetic	Add		ADD{cond}{S} Rd, Rn, <Oprnd2>	N Z C V		Rd := Rn + Oprnd2	
	with carry		ADC{cond}{S} Rd, Rn, <Oprnd2>	N Z C V		Rd := Rn + Oprnd2 + Carry	
	saturating	5E	QADD{cond} Rd, Rm, Rn		Q	Rd := SAT(Rm + Rn)	No shift/rotate.
	double saturating	5E	QDADD{cond} Rd, Rm, Rn		Q	Rd := SAT(Rm + SAT(Rn * 2))	No shift/rotate.
	Subtract		SUB{cond}{S} Rd, Rn, <Oprnd2>	N Z C V		Rd := Rn - Oprnd2	
	with carry		SBC{cond}{S} Rd, Rn, <Oprnd2>	N Z C V		Rd := Rn - Oprnd2 - NOT(Carry)	
	reverse subtract		RSB{cond}{S} Rd, Rn, <Oprnd2>	N Z C V		Rd := Oprnd2 - Rn	
	reverse subtract with carry		RSC{cond}{S} Rd, Rn, <Oprnd2>	N Z C V		Rd := Oprnd2 - Rn - NOT(Carry)	
	saturating	5E	QSUB{cond} Rd, Rm, Rn		Q	Rd := SAT(Rm - Rn)	No shift/rotate.
	double saturating	5E	QDSUB{cond} Rd, Rm, Rn		Q	Rd := SAT(Rm - SAT(Rn * 2))	No shift/rotate.
	Multiply	2	MUL{cond}{S} Rd, Rm, Rs	N Z C*		Rd := (Rm * Rs)[31:0]	
	accumulate	2	MLA{cond}{S} Rd, Rm, Rs, Rn	N Z C*		Rd := ((Rm * Rs) + Rn)[31:0]	
	unsigned long	M	UMULL{cond}{S} RdLo, RdHi, Rm, Rs	N Z C* V*		RdHi,RdLo := unsigned(Rm * Rs)	
	unsigned accumulate long	M	UMLAL{cond}{S} RdLo, RdHi, Rm, Rs	N Z C* V*		RdHi,RdLo := unsigned(RdHi,RdLo + Rm * Rs)	
	signed long	M	SMULL{cond}{S} RdLo, RdHi, Rm, Rs	N Z C* V*		RdHi,RdLo := signed(Rm * Rs)	
	signed accumulate long	M	SMLAL{cond}{S} RdLo, RdHi, Rm, Rs	N Z C* V*		RdHi,RdLo := signed(RdHi,RdLo + Rm * Rs)	
	signed 16 * 16 bit	5E	SMULxy{cond} Rd, Rm, Rs			Rd := Rm[x] * Rs[y]	No shift/rotate.
	signed 32 * 16 bit	5E	SMULWy{cond} Rd, Rm, Rs			Rd := (Rm * Rs[y])[47:16]	No shift/rotate.
	signed accumulate 16 * 16	5E	SMLAxy{cond} Rd, Rm, Rs, Rn		Q	Rd := Rn + Rm[x] * Rs[y]	No shift/rotate.
	signed accumulate 32 * 16	5E	SMLAWy{cond} Rd, Rm, Rs, Rn		Q	Rd := Rn + (Rm * Rs[y])[47:16]	No shift/rotate.
	signed accumulate long 16 * 16	5E	SMLALxy{cond} RdLo, RdHi, Rm, Rs			RdHi,RdLo := RdHi,RdLo + Rm[x] * Rs[y]	No shift/rotate.
	Count leading zeroes	5	CLZ{cond} Rd, Rm			Rd := number of leading zeroes in Rm	
Logical	Test		TST{cond} Rn, <Oprnd2>	N Z C		Update CPSR flags on Rn AND Oprnd2	
	Test equivalence		TEQ{cond} Rn, <Oprnd2>	N Z C		Update CPSR flags on Rn EOR Oprnd2	
	AND		AND{cond}{S} Rd, Rn, <Oprnd2>	N Z C		Rd := Rn AND Oprnd2	
	EOR		EOR{cond}{S} Rd, Rn, <Oprnd2>	N Z C		Rd := Rn EOR Oprnd2	
	ORR		ORR{cond}{S} Rd, Rn, <Oprnd2>	N Z C		Rd := Rn OR Oprnd2	
	Bit Clear		BIC{cond}{S} Rd, Rn, <Oprnd2>	N Z C		Rd := Rn AND NOT Oprnd2	
	No operation		NOP			R0 := R0	Flags not affected.
	Shift/Rotate						See Table **Operand 2.**
Compare	Compare		CMP{cond} Rn, <Oprnd2>	N Z C V		Update CPSR flags on Rn - Oprnd2	
	negative		CMN{cond} Rn, <Oprnd2>	N Z C V		Update CPSR flags on Rn + Oprnd2	

Vector Floating Point Instruction Set
Quick Reference Card

Key to Tables	
{cond}	See Table **Condition Field** (on ARM side).
<S/D>	S (single precision) or D (double precision).
<S/D/X>	As above, or X (unspecified precision).
Fd, Fn, Fm	Sd, Sn, Sm (single precision), or Dd, Dn, Dm (double precision).

{E}	E : raise exception on any NaN. Without E : raise exception only on signaling NaNs.
{Z}	Round towards zero. Overrides FPSCR rounding mode.
<VFPregs>	A comma separated list of *consecutive* VFP registers, enclosed in braces ({ and }).
<VFPsysreg>	FPSCR, or FPSID.

Operation		Assembler	Exceptions	Action	Notes
Vector arithmetic	Multiply	FMUL<S/D>{cond} Fd, Fn, Fm	IO, OF, UF, IX	Fd := Fn * Fm	
	negative	FNMUL<S/D>{cond} Fd, Fn, Fm	IO, OF, UF, IX	Fd := - (Fn * Fm)	
	accumulate	FMAC<S/D>{cond} Fd, Fn, Fm	IO, OF, UF, IX	Fd := Fd + (Fn * Fm)	
	deduct	FNMAC<S/D>{cond} Fd, Fn, Fm	IO, OF, UF, IX	Fd := Fd - (Fn * Fm)	
	negate and accumulate	FMSC<S/D>{cond} Fd, Fn, Fm	IO, OF, UF, IX	Fd := -Fd + (Fn * Fm)	
	negate and deduct	FNMSC<S/D>{cond} Fd, Fn, Fm	IO, OF, UF, IX	Fd := -Fd - (Fn * Fm)	
	Add	FADD<S/D>{cond} Fd, Fn, Fm	IO, OF, IX	Fd := Fn + Fm	
	Subtract	FSUB<S/D>{cond} Fd, Fn, Fm	IO, OF, IX	Fd := Fn - Fm	
	Divide	FDIV<S/D>{cond} Fd, Fn, Fm	IO, DZ, OF, UF, IX	Fd := Fn / Fm	
	Copy	FCPY<S/D>{cond} Fd, Fm		Fd := Fm	
	Absolute	FABS<S/D>{cond} Fd, Fm		Fd := abs(Fm)	
	Negative	FNEG<S/D>{cond} Fd, Fm		Fd := -Fm	
	Square root	FSQRT<S/D>{cond} Fd, Fm	IO, IX	Fd := sqrt(Fm)	
Scalar compare		FCMP{E}<S/D>{cond} Fd, Fm	IO	Set FPSCR flags on Fd - Fm	Use FMSTAT to transfer flags.
	Compare with zero	FCMP{E}Z<S/D>{cond} Fd	IO	Set FPSCR flags on Fd - 0	Use FMSTAT to transfer flags.
Scalar convert	Single to double	FCVTDS{cond} Dd, Sm	IO	Dd := convertStoD(Sm)	
	Double to single	FCVTSD{cond} Sd, Dm	IO, OF, UF, IX	Sd := convertDtoS(Dm)	
	Unsigned integer to float	FUITO<S/D>{cond} Fd, Sm		Fd := convertUItoF(Sm)	
	Signed integer to float	FSITO<S/D>{cond} Fd, Sm	IX	Fd := convertSItoF(Sm)	
	Float to unsigned integer	FTOUI{Z}<S/D>{cond} Sd, Fm	IO, IX	Sd := convertFtoUI(Fm)	
	Float to signed integer	FTOSI{Z}<S/D>{cond} Sd, Fm	IO, IX	Sd := convertFtoSI(Fm)	
Save VFP registers		FST<S/D>{cond} Fd, [Rn{, #<immed_8*4>}]		[address] := Fd	
	Multiple, unindexed	FSTMIA<S/D/X>{cond} Rn, <VFPregs>		Saves list of VFP registers, starting at address in Rn.	
	increment after	FSTMIA<S/D/X>{cond} Rn!, <VFPregs>		synonym: FSTMEA (empty ascending)	
	decrement before	FSTMDB<S/D/X>{cond} Rn!, <VFPregs>		synonym: FSTMFD (full descending)	
Load VFP registers		FLD<S/D>{cond} Fd, [Rn{, #<immed_8*4>}]		Fd := [address]	
	Multiple, unindexed	FLDMIA<S/D/X>{cond} Rn, <VFPregs>		Loads list of VFP registers, starting at address in Rn.	
	increment after	FLDMIA<S/D/X>{cond} Rn!, <VFPregs>		synonym: FLDMFD (full descending)	
	decrement before	FLDMDB<S/D/X>{cond} Rn!, <VFPregs>		synonym: FLDMEA (empty ascending)	
Transfer registers	ARM to single	FMSR{cond} Sn, Rd		Sn := Rd	
	Single to ARM	FMRS{cond} Rd, Sn		Rd := Sn	
	ARM to lower half of double	FMDLR{cond} Dn, Rd		Dn[31:0] := Rd	Use with FMDHR.
	Lower half of double to ARM	FMRDL{cond} Rd, Dn		Rd := Dn[31:0]	Use with FMRDH.
	ARM to upper half of double	FMDHR{cond} Dn, Rd		Dn[63:32] := Rd	Use with FMDLR.
	Upper half of double to ARM	FMRDH{cond} Rd, Dn		Rd := Dn[63:32]	Use with FMRDL.
	ARM to VFP system register	FMXR{cond} <VFPsysreg>, Rd		VFPsysreg := Rd	Stalls ARM until all VFP ops complete.
	VFP system register to ARM	FMRX{cond} Rd, <VFPsysreg>		Rd := VFPsysreg	Stalls ARM until all VFP ops complete.
	FPSCR flags to CPSR	FMSTAT{cond}		CPSR flags := FPSCR flags	Equivalent to FMRX R15, FPSCR

Exceptions	
IO	Invalid operation
OF	Overflow
UF	Underflow
IX	Inexact result
DZ	Division by zero

FPSCR format								Rounding		(Stride - 1)*3			Vector length - 1				Exception trap enable bits								Cumulative exception bits				
31	30	29	28				24	23	22	21	20		18	17	16		12	11	10	9	8				4	3	2	1	0
N	Z	C	V				FZ	RMODE		STRIDE			LEN				IXE	UFE	OFE	DZE	IOE				IXC	UFC	OFC	DZC	IOC

FZ: 1 = flush to zero mode. Rounding: 0 = round to nearest, 1 = towards +∞, 2 = towards -∞, 3 = towards zero. (Vector length * Stride) must not exceed 4 for double precision operands.

If Fd is S0-S7 or D0-D3, operation is Scalar (regardless of vector length).	If Fd is S8-S31 or D4-D15, and Fm is S0-S7 or D0-D3, operation is Mixed (Fm scalar, others vector).
If Fd is S8-S31 or D4-D15, and Fm is S8-S31 or D4-D15, operation is Vector.	S0-S7 (or D0-D3), S8-S15 (D4-D7), S16-S23 (D8-D11), S24-S31 (D12-D15) each form a circulating bank of registers.

Thumb Instruction Set
Quick Reference Card

All Thumb registers are Lo (R0-R7) except where specified. Hi registers are R8-R15.

Operation		§	Assembler	Update flags	Action	Notes
Move	Immediate		`MOV Rd, #<immed_8>`	✓	Rd := immed_8	8-bit immediate value.
	Lo to Lo		`MOV Rd, Rm`	✓	Rd := Rm	
	Hi to Lo, Lo to Hi, Hi to Hi		`MOV Rd, Rm`	×	Rd := Rm	Not Lo to Lo
Arithmetic	Add		`ADD Rd, Rn, #<immed_3>`	✓	Rd := Rn + immed_3	3-bit immediate value.
	Lo and Lo		`ADD Rd, Rn, Rm`	✓	Rd := Rn + Rm	
	Hi to Lo, Lo to Hi, Hi to Hi		`ADD Rd, Rm`	×	Rd := Rd + Rm	Not Lo to Lo
	immediate		`ADD Rd, #<immed_8>`	✓	Rd := Rd + immed_8	8-bit immediate value.
	with carry		`ADC Rd, Rm`	✓	Rd := Rd + Rm + C-bit	
	value to SP		`ADD SP, #<immed_7*4>`	×	SP := SP + immed_7 * 4	9-bit immediate value (word-aligned).
	form address from SP		`ADD Rd, SP, #<immed_8*4>`	×	Rd := SP + immed_8 * 4	10-bit immediate value (word-aligned).
	form address from PC		`ADD Rd, PC, #<immed_8*4>`	×	Rd := (PC AND 0xFFFFFFFC) + immed_8 * 4	10-bit immediate value (word-aligned).
	Subtract		`SUB Rd, Rn, Rm`	✓	Rd := Rn - Rm	
	immediate 3		`SUB Rd, Rn, #<immed_3>`	✓	Rd := Rn - immed_3	3-bit immediate value.
	immediate 8		`SUB Rd, #<immed_8>`	✓	Rd := Rd - immed_8	8-bit immediate value.
	with carry		`SBC Rd, Rm`	✓	Rd := Rd - Rm - NOT C-bit	
	value from SP		`SUB SP, #<immed_7*4>`	×	SP := SP - immed_7 * 4	9-bit immediate value (word-aligned).
	Negate		`NEG Rd, Rm`	✓	Rd := - Rm	
	Multiply		`MUL Rd, Rm`	✓	Rd := Rm * Rd	
	Compare		`CMP Rn, Rm`	✓	update CPSR flags on Rn - Rm	Can be Lo to Lo, Lo to Hi, Hi to Lo, or Hi to Hi.
	negative		`CMN Rn, Rm`	✓	update CPSR flags on Rn + Rm	
	immediate		`CMP Rn, #<immed_8>`	✓	update CPSR flags on Rn - immed_8	8-bit immediate value.
	No operation		`NOP`	×	R8 := R8	Flags not affected.
Logical	AND		`AND Rd, Rm`	✓	Rd := Rd AND Rm	
	Exclusive OR		`EOR Rd, Rm`	✓	Rd := Rd EOR Rm	
	OR		`ORR Rd, Rm`	✓	Rd := Rd OR Rm	
	Bit clear		`BIC Rd, Rm`	✓	Rd := Rd AND NOT Rm	
	Move NOT		`MVN Rd, Rm`	✓	Rd := NOT Rm	
	Test bits		`TST Rn, Rm`	✓	update CPSR flags on Rn AND Rm	
Shift/rotate	Logical shift left		`LSL Rd, Rm, #<immed_5>`	✓	Rd := Rm << immed_5	5-bit immediate shift. Allowed shifts 0-31.
			`LSL Rd, Rs`	✓	Rd := Rd << Rs	
	Logical shift right		`LSR Rd, Rm, #<immed_5>`	✓	Rd := Rm >> immed_5	5-bit immediate shift. Allowed shifts 1-32.
			`LSR Rd, Rs`	✓	Rd := Rd >> Rs	
	Arithmetic shift right		`ASR Rd, Rm, #<immed_5>`	✓	Rd := Rm ASR immed_5	5-bit immediate shift. Allowed shifts 1-32.
			`ASR Rd, Rs`	✓	Rd := Rd ASR Rs	
	Rotate right		`ROR Rd, Rs`	✓	Rd := Rd ROR Rs	
Branch	Conditional branch		`B{cond} label`		R15 := label	label must be within -252 to +258 bytes of current instruction. See Table Condition Field (ARM side). AL not allowed.
	Unconditional branch		`B label`		R15 := label	label must be within ±2Kb of current instruction.
	Long branch with link		`BL label`		R14 := R15 - 2, R15 := label	Encoded as two Thumb instructions. label must be within ±4Mb of current instruction.
	Branch and exchange		`BX Rm`		R15 := Rm AND 0xFFFFFFFE	Change to ARM state if Rm[0] = 0.
	Branch with link and exchange	5T	`BLX label`		R14 := R15 - 2, R15 := label Change to ARM	Encoded as two Thumb instructions. label must be within ±4Mb of current instruction.
	Branch with link and exchange	5T	`BLX Rm`		R14 := R15 - 2, R15 := Rm AND 0xFFFFFFFE Change to ARM if Rm[0] = 0	
Software Interrupt			`SWI <immed_8>`		Software interrupt processor exception	8-bit immediate value encoded in instruction.
Breakpoint		5T	`BKPT <immed_8>`		Prefetch abort *or* enter debug state	

Thumb Instruction Set
Quick Reference Card

Operation		§	Assembler	Action	Notes
Load	with immediate offset, word		`LDR Rd, [Rn, #<immed_5*4>]`	Rd := [Rn + immed_5 * 4]	
	halfword		`LDRH Rd, [Rn, #<immed_5*2>]`	Rd := ZeroExtend([Rn + immed_5 * 2][15:0])	Clears bits 31:16
	byte		`LDRB Rd, [Rn, #<immed_5>]`	Rd := ZeroExtend([Rn + immed_5][7:0])	Clears bits 31:8
	with register offset, word		`LDR Rd, [Rn, Rm]`	Rd := [Rn + Rm]	
	halfword		`LDRH Rd, [Rn, Rm]`	Rd := ZeroExtend([Rn + Rm][15:0])	Clears bits 31:16
	signed halfword		`LDRSH Rd, [Rn, Rm]`	Rd := SignExtend([Rn + Rm][15:0])	Sets bits 31:16 to bit 15
	byte		`LDRB Rd, [Rn, Rm]`	Rd := ZeroExtend([Rn + Rm][7:0])	Clears bits 31:8
	signed byte		`LDRSB Rd, [Rn, Rm]`	Rd := SignExtend([Rn + Rm][7:0])	Sets bits 31:8 to bit 7
	PC-relative		`LDR Rd, [PC, #<immed_8*4>]`	Rd := [(PC AND 0xFFFFFFFC) + immed_8 * 4]	
	SP-relative		`LDR Rd, [SP, #<immed_8*4>]`	Rd := [SP + immed_8 * 4]	
	Multiple		`LDMIA Rn!, <reglist>`	Loads list of registers	Always updates base register.
Store	with immediate offset, word		`STR Rd, [Rn, #<immed_5*4>]`	[Rn + immed_5 * 4] := Rd	
	halfword		`STRH Rd, [Rn, #<immed_5*2>]`	[Rn + immed_5 * 2][15:0] := Rd[15:0]	Ignores Rd[31:16]
	byte		`STRB Rd, [Rn, #<immed_5>]`	[Rn + immed_5][7:0] := Rd[7:0]	Ignores Rd[31:8]
	with register offset, word		`STR Rd, [Rn, Rm]`	[Rn + Rm] := Rd	
	halfword		`STRH Rd, [Rn, Rm]`	[Rn + Rm][15:0] := Rd[15:0]	Ignores Rd[31:16]
	byte		`STRB Rd, [Rn, Rm]`	[Rn + Rm][7:0] := Rd[7:0]	Ignores Rd[31:8]
	SP-relative, word		`STR Rd, [SP, #<immed_8*4>]`	[SP + immed_8 * 4] := Rd	
	Multiple		`STMIA Rn!, <reglist>`	Stores list of registers	Always updates base register.
Push/ Pop	Push		`PUSH <reglist>`	Push registers onto stack	Full descending stack.
	Push with link		`PUSH <reglist, LR>`	Push LR and registers onto stack	
	Pop		`POP <reglist>`	Pop registers from stack	
	Pop and return		`POP <reglist, PC>`	Pop registers, branch to address loaded to PC	
	Pop and return with exchange	5T	`POP <reglist, PC>`	Pop, branch, and change to ARM state if address[0] = 0	

Document Number

ARM QRC 0001D

Change Log

Issue	Date	By	Change
A	June 1995	BJH	First Release
B	Sept 1996	BJH	Second Release
C	Nov 1998	BJH	Third Release
D	Oct 1999	CKS	Fourth Release

ENGLAND
ARM Ltd
Fulbourn Road
Cherry Hinton
Cambridge CB1 9JN
UK

Telephone: +44 1223 400400
Facsimile: +44 1223 400410
Email: info@arm.com

GERMANY
ARM Ltd
Otto-Hahn Str. 13b
85521 Ottobrun-Riemerling
Munich
Germany

Telephone: +49 89 608 75545
Facsimile: +49 98 608 75599
Email: info@arm.com

USA
ARM Inc
750 University Avenue
Suite 150,
Los Gatos CA 95032
USA

Telephone: +1 408 579 2207
Facsimile: +1 408 579 1205
Email: info@arm.com

JAPAN
ARM KK
Plustaria Building 4F,
3-1-4 Shinyokohama, Kohoku-ku,
Yokohama-shi, 222-0033
Japan

Telephone: +81 45 477 5260
Facsimile: +81 45 477 5261
Email: info@arm.com

KOREA
ARM
Room #1115, Hyundai Building
9-4, Soonae-Dong, Boondang-Ku
Sungnam, Kyunggi-Do
Korea 463-020

Telephone: +82 342 712 8234
Facsimile: +82 342 713 8225
Email: info@arm.com

ARM Instruction Set
Quick Reference Card

Operation		§	Assembler	Action	Notes
Branch	Branch		`B{cond} label`	R15 := label	label must be within ±32Mb of current instruction.
	with link		`BL{cond} label`	R14 := R15-4, R15 := label	label must be within ±32Mb of current instruction.
	and exchange	4T	`BX{cond} Rm`	R15 := Rm, Change to Thumb if Rm[0] is 1	
	with link and exchange (1)	5T	`BLX label`	R14 := R15 - 4, R15 := label, Change to Thumb	Cannot be conditional.
	with link and exchange (2)	5T	`BLX{cond} Rm`	R14 := R15 - 4, R15 := Rm[31:1] Change to Thumb if Rm[0] is 1	label must be within ±32Mb of current instruction.
Load	Word		`LDR{cond} Rd, <a_mode2>`	Rd := [address]	
	User mode privilege		`LDR{cond}T Rd, <a_mode2P>`		
	branch (and exchange)		`LDR{cond} R15, <a_mode2>`	R15 := [address][31:1] (§ 5T: Change to Thumb if [address][0] is 1)	
	Byte		`LDR{cond}B Rd, <a_mode2>`	Rd := ZeroExtend[byte from address]	
	User mode privilege		`LDR{cond}BT Rd, <a_mode2P>`		
	signed	4	`LDR{cond}SB Rd, <a_mode3>`	Rd := SignExtend[byte from address]	
	Halfword	4	`LDR{cond}H Rd, <a_mode3>`	Rd := ZeroExtent[halfword from address]	
	signed	4	`LDR{cond}SH Rd, <a_mode3>`	Rd := SignExtend[halfword from address]	
Load multiple	Pop, or Block data load		`LDM{cond}<a_mode4L> Rd{!}, <reglist-pc>`	Load list of registers from [Rd]	
	return (and exchange)		`LDM{cond}<a_mode4L> Rd{!}, <reglist+pc>`	Load registers, R15 := [address][31:1] (§ 5T: Change to Thumb if [address][0] is 1)	
	and restore CPSR		`LDM{cond}<a_mode4L> Rd{!}, <reglist+pc>^`	Load registers, branch (§ 5T: and exchange), CPSR := SPSR	Use from exception modes only.
	User mode registers		`LDM{cond}<a_mode4L> Rd, <reglist-pc>^`	Load list of User mode registers from [Rd]	Use from privileged modes only.
Store	Word		`STR{cond} Rd, <a_mode2>`	[address] := Rd	
	User mode privilege		`STR{cond}T Rd, <a_mode2P>`	[address] := Rd	
	Byte		`STR{cond}B Rd, <a_mode2>`	[address][7:0] := Rd[7:0]	
	User mode privilege		`STR{cond}BT Rd, <a_mode2P>`	[address][7:0] := Rd[7:0]	
	Halfword	4	`STR{cond}H Rd, <a_mode3>`	[address][15:0] := Rd[15:0]	
Store multiple	Push, or Block data store		`STM{cond}<a_mode4S> Rd{!}, <reglist>`	Store list of registers to [Rd]	
	User mode registers		`STM{cond}<a_mode4S> Rd{!}, <reglist>^`	Store list of User mode registers to [Rd]	Use from privileged modes only.
Swap	Word	3	`SWP{cond} Rd, Rm, [Rn]`	temp := [Rn], [Rn] := Rm, Rd := temp	
	Byte	3	`SWP{cond}B Rd, Rm, [Rn]`	temp := ZeroExtend([Rn][7:0]), [Rn][7:0] := Rm[7:0], Rd := temp	
Coprocessors	Data operations	2	`CDP{cond} p<cpnum>, <op1>, CRd, CRn, CRm, <op2>`	Coprocessor defined	
		5	`CDP2 p<cpnum>, <op1>, CRd, CRn, CRm, <op2>`		Cannot be conditional.
	Move to ARM reg from coproc	2	`MRC{cond} p<cpnum>, <op1>, Rd, CRn, CRm, <op2>`		
		5	`MRC2 p<cpnum>, <op1>, Rd, CRn, CRm, <op2>`		Cannot be conditional.
	Move to coproc from ARM reg	2	`MCR{cond} p<cpnum>, <op1>, Rd, CRn, CRm, <op2>`		
		5	`MCR2 p<cpnum>, <op1>, Rd, CRn, CRm, <op2>`		Cannot be conditional.
	Load	2	`LDC{cond} p<cpnum>, CRd, <a_mode5>`		
		5	`LDC2 p<cpnum>, CRd, <a_mode5>`		Cannot be conditional.
	Store	2	`STC{cond} p<cpnum>, CRd, <a_mode5>`		
		5	`STC2 p<cpnum>, CRd, <a_mode5>`		Cannot be conditional.
Software interrupt			`SWI{cond} <immed_24>`	Software interrupt processor exception	24-bit value encoded in instruction.
Breakpoint		5	`BKPT <immed_16>`	Prefetch abort *or* enter debug state	Cannot be conditional.

ARM Addressing Modes
Quick Reference Card

Addressing Mode 2 - Word and Unsigned Byte Data Transfer			
Pre-indexed	Immediate offset	`[Rn, #+/-<immed_12>]{!}`	
	Zero offset	`[Rn]`	Equivalent to [Rn,#0]
	Register offset	`[Rn, +/-Rm]{!}`	
	Scaled register offset	`[Rn, +/-Rm, LSL #<immed_5>]{!}`	Allowed shifts 0-31
		`[Rn, +/-Rm, LSR #<immed_5>]{!}`	Allowed shifts 1-32
		`[Rn, +/-Rm, ASR #<immed_5>]{!}`	Allowed shifts 1-32
		`[Rn, +/-Rm, ROR #<immed_5>]{!}`	Allowed shifts 1-31
		`[Rn, +/-Rm, RRX]{!}`	
Post-indexed	Immediate offset	`[Rn], #+/-<immed_12>`	
	Register offset	`[Rn], +/-Rm`	
	Scaled register offset	`[Rn], +/-Rm, LSL #<immed_5>`	Allowed shifts 0-31
		`[Rn], +/-Rm, LSR #<immed_5>`	Allowed shifts 1-32
		`[Rn], +/-Rm, ASR #<immed_5>`	Allowed shifts 1-32
		`[Rn], +/-Rm, ROR #<immed_5>`	Allowed shifts 1-31
		`[Rn], +/-Rm, RRX`	

Addressing Mode 2 (Post-indexed only)			
Post-indexed	Immediate offset	`[Rn], #+/-<immed_12>`	
	Zero offset	`[Rn]`	Equivalent to [Rn],#0
	Register offset	`[Rn], +/-Rm`	
	Scaled register offset	`[Rn], +/-Rm, LSL #<immed_5>`	Allowed shifts 0-31
		`[Rn], +/-Rm, LSR #<immed_5>`	Allowed shifts 1-32
		`[Rn], +/-Rm, ASR #<immed_5>`	Allowed shifts 1-32
		`[Rn], +/-Rm, ROR #<immed_5>`	Allowed shifts 1-31
		`[Rn], +/-Rm, RRX`	

Addressing Mode 3 - Halfword and Signed Byte Data Transfer			
Pre-indexed	Immediate offset	`[Rn, #+/-<immed_8>]{!}`	
	Zero offset	`[Rn]`	Equivalent to [Rn,#0]
	Register	`[Rn, +/-Rm]{!}`	
Post-indexed	Immediate offset	`[Rn], #+/-<immed_8>`	
	Register	`[Rn], +/-Rm`	

Addressing Mode 4 - Multiple Data Transfer			
Block load		**Stack pop**	
`IA`	Increment After	`FD`	Full Descending
`IB`	Increment Before	`ED`	Empty Descending
`DA`	Decrement After	`FA`	Full Ascending
`DB`	Decrement Before	`EA`	Empty Ascending
Block store		**Stack push**	
`IA`	Increment After	`EA`	Empty Ascending
`IB`	Increment Before	`FA`	Full Ascending
`DA`	Decrement After	`ED`	Empty Descending
`DB`	Decrement Before	`FD`	Full Descending

Addressing Mode 5 - Coprocessor Data Transfer			
Pre-indexed	Immediate offset	`[Rn, #+/-<immed_8*4>]{!}`	
	Zero offset	`[Rn]`	Equivalent to [Rn,#0]
Post-indexed	Immediate offset	`[Rn], #+/-<immed_8*4>`	
Unindexed	No offset	`[Rn], {8-bit copro. option}`	

ARM architecture versions	
n	ARM architecture version *n* and above.
*n*T	T variants of ARM architecture version *n* and above.
M	ARM architecture version 3M, and 4 and above excluding xM variants
*n*E	E variants of ARM architecture version *n* and above.

Operand 2		
Immediate value	`#<immed_8r>`	
Logical shift left immediate	`Rm, LSL #<immed_5>`	Allowed shifts 0-31
Logical shift right immediate	`Rm, LSR #<immed_5>`	Allowed shifts 1-32
Arithmetic shift right immediate	`Rm, ASR #<immed_5>`	Allowed shifts 1-32
Rotate right immediate	`Rm, ROR #<immed_5>`	Allowed shifts 1-31
Register	`Rm`	
Rotate right extended	`Rm, RRX`	
Logical shift left register	`Rm, LSL Rs`	
Logical shift right register	`Rm, LSR Rs`	
Arithmetic shift right register	`Rm, ASR Rs`	
Rotate right register	`Rm, ROR Rs`	

PSR fields (use at least one suffix)		
Suffix	**Meaning**	
`c`	Control field mask byte	PSR[7:0]
`f`	Flags field mask byte	PSR[31:24]
`s`	Status field mask byte	PSR[23:16]
`x`	Extension field mask byte	PSR[15:8]

Condition Field {cond}		
Mnemonic	**Description**	**Description (VFP)**
`EQ`	Equal	Equal
`NE`	Not equal	Not equal, or unordered
`CS / HS`	Carry Set / Unsigned higher or same	Greater than or equal, or unordered
`CC / LO`	Carry Clear / Unsigned lower	Less than
`MI`	Negative	Less than
`PL`	Positive or zero	Greater than or equal, or unordered
`VS`	Overflow	Unordered (at least one NaN operand)
`VC`	No overflow	Not unordered
`HI`	Unsigned higher	Greater than, or unordered
`LS`	Unsigned lower or same	Less than or equal
`GE`	Signed greater than or equal	Greater than or equal
`LT`	Signed less than	Less than, or unordered
`GT`	Signed greater than	Greater than
`LE`	Signed less than or equal	Less than or equal, or unordered
`AL`	Always (normally omitted)	Always (normally omitted)

Key to tables	
`{!}`	Updates base register after data transfer if ! present. (Post-indexed always updates.)
`<immed_8r>`	A 32-bit constant, formed by right-rotating an 8-bit value by an even number of bits.
`+/-`	+ or -. (+ may be omitted.)